

# SERVICE NEWS

SUBARU CORPORATION

HEAD OFFICE ; EBISU SUBARU BLDG.  
SHIBUYA, TOKYO, JAPAN

~~3048~~ APPROVED

NO. 200-035      DATE September 11,2017      (SUPERSEDES NO.      )  
REV. XXXXXXXX      DATE XXXXXXXX      (SUPERSEDES NO.      )  
REASON XXXXXXXX

## Notices from Manufacturer for Engine Problem

This service news is being issued to inform owners and operators that FAA's AD and manufacturer's SB have been published as follows for all types of Lycoming engines (O-320-D2A, IO-360-B1B, AEIO-360-B1B and O-360-A5AD) used in FA-200.

- (1) FAA AD No.2017-16-11 (published on August 10, 2017)
- (2) LYCOMING MANDATORY SERVICE BULLETIN No.632B (published on August 4, 2017)

These documents refer to a problem in the connecting rod of these engines and provide instructions to avoid the problem, which may cause engine problems or an engine halt in flight.

Please check these documents for engine serial numbers and repair/overhaul conditions to determine if your engine is applicable.